



## BIOS Update Release Notes

### PRODUCTS: STK1AW32SC, STK1A32SC (Standard BIOS)

**BIOS Version 0044 - SCCHTAX5.86A.0044.2019.0620.2044**

#### About This Release:

- Date: June 20, 2019
- TXE Firmware: 2.00.05.3105
- Framework BIOS Reference Code: Based on 3.4
- Integrated Graphics:
  - Option ROM: 9.0.1046
  - UEFI Driver: 9.0.1056

#### New Fixes/Features:

Updated BIOS code for security fixes.

**BIOS Version 0043 - SCCHTAX5.86A.0043.2019.0408.1421**

#### About This Release:

- Date: April 8, 2019
- TXE Firmware: 2.00.05.3105
- Framework BIOS Reference Code: Based on 3.4
- Integrated Graphics
  - Option ROM: 9.0.1046
  - UEFI Driver: 9.0.1056

#### New Fixes/Features:

- Updated BIOS code for security fixes.

**BIOS Version 0041 - SCCHTAX5.86A.0041.2018.0620.1803**

#### About This Release:

- Date: June 08, 2018
- TXE Firmware: 2.00.05.3105
- Framework BIOS Reference Code: Based on 3.4
- Integrated Graphics
  - Option ROM: 9.0.1046
  - UEFI Driver: 9.0.1056

#### New Fixes/Features:

- Security enhancements.
- Added a workaround for an issue that caused no display when waking from S3 when RC6 remote was enabled.

**BIOS Update 0040 - SCCHTAX5.86A.0040.2018.0313.1442**

#### About This Release:

- Date: March 13, 2018
- XE Firmware: 2.00.05.3105

\*Other names and brands may be claimed as the property of others.

- Framework BIOS Reference Code: Based on 3.4
- Integrated Graphics
  - Option ROM: 9.0.1046
  - UEFI Driver: 9.0.1056

**New Fixes/Features:**

- Updated CPU Microcode (Security Advisory-00088)

**BIOS Version 0038 - SCCHTAX5.86A.0038.2017.1127.1755**

**About This Release:**

- Date: November 8, 2017
- TXE Firmware: 2.00.05.3105
- Framework BIOS Reference Code: Based on 3.4
- Integrated Graphics:
  - Option ROM: 9.0.1046
  - UEFI Driver: 9.0.1056

**New Fixes/Features:**

- Security Enhancements.
- Add setup item: "Allow UEFI 3rd party driver loaded".
- Due to a security enhancement, it will not be possible to go to any BIOS earlier than BIOS 0038.

**BIOS Version 0037 - SCCHTAX5.86A.0037.2017.0914.1859**

**About This Release:**

- Date: September 14, 2017
- TXE Firmware: 2.00.05.3105
- Framework BIOS Reference Code: Based on 3.4
- Integrated Graphics:
  - Option ROM: 9.0.1046
  - UEFI Driver: 9.0.1056

**New Fixes/Features:**

- Fixed issue where the BIOS would reset to defaults after pairing a Bluetooth keyboard.

**BIOS Version 0035 - SCCHTAX5.86A.0035.2017.0410.1745**

**About This Release:**

- Date: April 10, 2017
- TXE Firmware: 2.00.05.3105
- Memory Reference Code: Based on 0.34.0.16.1
- Integrated Graphics
  - Option ROM: 9.0.1046
  - UEFI Driver: 9.0.1056

**New Fixes/Features:**

- Added workaround when black screen is occurs.

**BIOS Version 0034 - SCCHTAX5.86A.0034.2017.0302.1921**

**About This Release:**

- Date: March 19, 2017

\*Other names and brands may be claimed as the property of others.

- TXE Firmware: 2.00.05.3105
- Memory Reference Code: Based on 0.34.0.16.1
- Integrated Graphics
  - Option ROM: 9.0.1046
  - UEFI Driver: 9.0.1056

**New Fixes/Features:**

- Fixed issue where Power State setting in BIOS has no affect when set to Always Off.

**BIOS Version 0032 - SCCHTAX5.86A.0032.2017.0111.1339**

**About This Release:**

- Date: January 11, 2017
- TXE Firmware: 2.00.05.3105
- Memory Reference Code: Based on 0.34.0.16.1
- Integrated Graphics
  - Option ROM: 9.0.1046
  - UEFI Driver: 9.0.1056
- GOP Driver : 8.0.1037

**New Fixes/Features:**

- Security Enhancements.
- Updated USB RT#2 security solution.

**BIOS Version 0030 - SCCHTAX5.86A.0030.2016.1024.1920**

**About This Release:**

- Date: October 24, 2016
- TXE Firmware: 2.00.05.3105
- Framework BIOS Reference Code: Based on 3.0
- GOP Driver : 8.0.1037

**New Fixes/Features:**

- Security Enhancements.

**BIOS Version 0029 - SCCHTAX5.86A.0029.2016.0914.1508**

**About This Release:**

- Date: September 14, 2016
- TXE Firmware: 2.00.05.3105
- Framework BIOS Reference Code: Based on 3.0
- GOP Driver : 8.0.1037

**New Fixes/Features:**

- Security enhancements.
- Added android option.
- Update TCG to TCG10.
- Added item for PTT enable/disable.
- Added BT scan device solution.

**BIOS Version 0026 - SCCHTAX5.86A.0026.2016.0722.1307**

**About This Release:**

- Date: July 22, 2016
- TXE Firmware: 2.00.05.3105
- Framework BIOS Reference Code: Based on 3.0
- GOP Driver : 8.0.1037

**New Fixes/Features:**

- Fixed a Bluetooth keyboard sync issue.
- Updated Microcode.
- Update TXE to 02.00.05.3105

**BIOS Version 0024 - SCCHTAX5.86A.0024.2016.0408.1041**

**About This Release:**

- Date: April 8, 2016
- TXE Firmware: 2.0.4.3100
- Framework BIOS Reference Code: Based on 2.80
- GOP Driver : 8.0.1037

**New Fixes/Features:**

- Fixed issue where Intel Driver Update Utility does not return any driver suggestions during auto-scan.

**BIOS Version 0023 - SCCHTAX5.86A.0023.2016.0328.1333**

**About This Release:**

- Date: March 28, 2016
- TXE Firmware: 2.0.4.3100
- Framework BIOS Reference Code: Based on 2.80
- GOP Driver : 8.0.1037

**New Fixes/Features:**

- Fixed issue with Bluetooth\* keyboards.
- Enabled C States.
- Updated BIOS to allow system to boot normally if a .BIO file is not found using F4 recovery path.
- Updated processor support.
- Fixed issue where TXE error message appears at end of POST.
- Fixed issue with selecting items when prompted to Save & Exit or Discard Changes & Exit.
- Fixed issue where certain eMMC storage fails in F4 BIOS Recovery.
- Updated TXE firmware to version 2.0.4.3100.

**BIOS Version 0019 - SCCHTAX5.86A.0019.2016.0113.1043**

**About This Release:**

- Date: January 13, 2016
- TXE Firmware: 2.0.2.3095
- Framework BIOS Reference Code: Based on 2.80
- GOP Driver : 8.0.1037

**New Fixes/Features:**

- Fixed issue where the cursor sometimes lags in the BIOS Setup.

- Fixed issue on Windows 10 64-bit Operating Systems where Multi Phase Resume would fail.
- Added Bluetooth keyboard support.
- Fixed an issue where a device will not be seen via USB 3.0.
- Updated Processor support.
- Fixed an issue when selecting F2 via the power button menu, where the default setting of some items in BIOS Setup would change.
- Updated GOP to version 8.0.1037.
- Fixed an issue in the F7 menu where "unknown device" would display.
- Fixed an issue in the F7 menu where the USB device would disappear when "Refresh Media List" is selected.
- Fixed an issue where pressing the power button would behave like the enter key.
- Added a setup menu option so that "Wlan Dynamic Solution" can be selected.
- Added NTFS support.
- Updated TXE to version 2.0.2.3095
- Added an option for the Indonesia SKU to disallow the AC mode on the Intel wireless adapter.

<b>BIOS Version 0014 - SCCHTAX5.86A.0014.2015.1119.1410</b>
---

**About This Release:**

- Date: November 19, 2015
- TXE Firmware: 2.0.2. 3094
- Framework BIOS Reference Code: Based on 2.60
- GOP Driver : 8.0.1035

**New Fixes/Features:**

- Initial production BIOS release

---



---

**LEGAL INFORMATION**

---



---

**Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.**

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.  
Copyright (c) 2015 Intel Corporation.

\*Other names and brands may be claimed as the property of others.